

## Social Compliance Assessment Report

	<p>2.) The fire extinguisher sign was indicating a fire extinguisher, however, no fire extinguisher was present.</p> <p>29 CFR (2002) § 1910.157(c)(1)</p> <p><b>Note:</b> During the process of the audit, the fire extinguisher sign was removed from the wall by management.</p>
Are emergency alarms present, maintained and detectable by employees in accordance with applicable standards?	Yes
Are secondary emergency exits present and located in accordance with applicable standards?	Yes
Are emergency exits maintained in accordance with applicable standards?	<p>No</p> <p>No exit signs in the following areas of work; four colour printing room, clean room in building 3 and in the warehouse located in building 1.</p> <p>8 C.C.R (2009) § 3216</p> <p><b>Note:</b> During the process of the audit, management was able to place emergency "EXIT" signs in the locations that were missing emergency exit signs.</p>
Are emergency exit pathways present and maintained in accordance with applicable standards?	<p>No</p> <p>During the time of the facility tour, the auditor observed no directional signage to guide employees to the nearest exit in building 1 and in building 2.</p> <p>29 CFR (2002) § 1910.37(b)(4)</p> <p><b>Note:</b> At the time of the process of the audit, management went ahead and place directional signage in the areas that were missing guidance to the nearest exit route.</p>
Are evacuation plans present, posted and maintained in accordance with applicable standards?	Yes
Are emergency assembly points present and maintained in accordance with applicable standards?	Yes
Is emergency lighting present and maintained in accordance with applicable standards?	<p>No</p> <p>No emergency lighting was present in the 2nd building.</p>